

IETYMSC

Comparative Survey Report on Usage of Home Appliances

INTRODUCTION:

There are Various types of Home Appliances that available in our house. We have selected *Fan and Ironbox* as two of the Appliances for taking the report that we are used in our Day to Day life. These are the Essential things for our Day to Day life. To go anywhere we have to iron our dress and to make us safe from the hot climate in summer we use fans. If we see any house there is no house without this home Appliances. Here we have created a comparative report on *Fan and Iron box* from the consumer view point.

APPLIANCES AVAILABLE IN MARKET:

The Different companies Fan and Ironbox that are available in the market are listed below:

<i>IRONBOX</i>	<i>FAN</i>
Philips	Crompton Greaves
Bajaj	Orient
Vijay	Usha
Pilot	Polar
Alf	Rallifan
Butterfly	Toshiba
Anchor	Aristocrat
Toshiba	Honda
Ocarina	Mitaso
National	Breeze cool
Elba	Standard

REPORT:

Sl. No.	Product Name		Address of the Consumer	Report Date	Feedback (Likes and Dislikes about the product)	
	Fan	Iron box			Fan	Ironbox
1.	Crompton Greaves	Philips	M.Manoj, Kovilvilai, Mulagumodu(p.o)	1/9/2008	* Good Quality. * Low Cost. * Less Sound while operation.	* High Cost. * Long Life. * Good Quality.
2.	Usha	Philips	C.Ashok, Putarivilai, Irenipuram(p.o).	1/9/2008	* Low Cost. * Long Life. * Smooth Speed Control.	* Neat Iron. * Less Current Consuming. * Steam Iron.
3.	Crompton Greaves	National	M.Mani, Putarivilai, Irenipuram(p.o).	1/9/2008	* Good quality. * High speed. * Low Cost.	* Smooth Heat Control. * Long Life. * Good Quality.
4.	Usha	Philips	M.Rajan, Putarivilai, Irenipuram(p.o).	1/9/2008	* Long Life. * High mechanical strength. * Good quality.	* Less Weight. * Long Life. * High Quality.
5.	Crompton Greaves	Bajaj	G.Babu, Kaithakattuvilai, Irenipuram(p.o).	1/9/2008	* Low power consuming. * High quality. * Less sound is produced.	* Low Cost. * No Maintainance. * Steam Iron.
6.	Crompton Greaves	Toshiba	G.George, Kaithakattuvilai, Irenipuram(p.o).	1/9/2008	* High quality. * Present in various colors. * Low Cost.	* Long Life. * Tough Heat Control. * Frequent Maintainance Required.
7.	Orient	Philips	A.Resalam, Kaithakattuvilai, Irenipuram(p.o).	1/9/2008	* Low Cost. * No Sound. * Smooth Speed Control.	* Automatic Heat sensing. * Steam Iron. * High Quality.
8.	Usha	National	V.T.Vijayan, Kaithakattuvilai, Irenipuram (p.o).	1/9/2008	* Good mechanical strength. * Long life. * Low cost.	* Smooth Heat control. * Japan Technology. * High cost.
9.	Usha	Vijay	R.Rathenaswamy, Kaithakattuvilai, Irenipuram (p.o).	1/9/2008	* High Quality. * Low cost . * Long life.	* Less Weight. * Long Life. * High Quality.
10.	Crompton Greaves	Philips	R.Rajan, Kaithakattuvilai, Irenipuram (p.o).	1/9/2008	* Smooth speed control. * Cool breeze. * Low cost.	* Steam Iron. * Low power consuming. * Less weight.
11.	Usha	Alfa	G.Henry, Kaithakattuvilai, Irenipuram (p.o).	1/9/2008	* Low Cost * High Quality. * Good mechanical strength.	* Less Weight. * Maintainance Required. * Low Quality.
12.	Crompton Greaves	Philips	H.Rathenam, Kaithakattuvilai, Irenipuram(p.o).	1/9/2008	* Low power consuming. * High quality. * Less sound is produced.	* Smooth Iron. * Less Weight. * High Quality.
13.	Usha	Bajaj	T.R.Joel Lyte, Kaithakattuvilai, Irenipuram(p.o).	1/9/2008	* Low Cost. * Long Life. * Smooth Speed Control.	* Less Weight. * Long Life. * High Quality.
14.	Rallifan	Anchor	P.Thankaraj, Kaithakattuvilai, Irenipuram(p.o).	1/9/2008	* Consume less power. * Low cost. * Maintainance Required.	* Over Heating. * No automatic heat control.. * Damage the clothes.
15.	Standard	Pilot	R.Shibin, Kaithakattuvilai, Irenipuram(p.o).	1/9/2008	* Over Heating of Regulator. * Low Cost. * Maintainance Required.	* Less Weight. * Long Life. * High Quality.

16.	Orient	National	R.Kanagamani, Paramankarai, Irenipuram(p.o).	2/9/2008	* Low Cost. * No Sound. * Smooth Speed Control.	* Japan Technology. * Quality is good. * Neat Iron.
17.	Crompton Greaves	Toshiba	P.Jai Suresh, Paramankarai, Irenipuram(p.o).	2/9/2008	* Low power consuming. * High quality. * Less sound is produced.	* Risk of shock. * Less Weight. * Low Quality Cable.
18.	Crompton Greaves	National	R.Darvin, Paramankarai, Irenipuram(p.o).	2/9/2008	* Smooth speed control. * Cool breeze. * Low cost.	* High Weight. * Long Life. * High Quality.
19.	Usha	Toshiba	A.Lazer, Paramankarai, Irenipuram(p.o).	2/9/2008	* Low Cost. * Long Life. * Smooth Speed Control.	* Long Life. * Tough Heat Control. * Frequent Maintainance Required.
20.	Usha	Pilot	R.Johnrose, Paramankarai, Irenipuram(p.o).	2/9/2008	* Long Life. * High mechanical strength. * Good quality.	* Low Quality. * Over Heating. * Damage to Clothes.
21.	Honda	Bajaj	A.Dennis, Paramankarai, Irenipuram(p.o).	2/9/2008	* Low Quality. * Humming sound is heard. * Consume Large Power.	* Low Cost. * No Maintainance. * Steam Iron.
22.	Usha	Butterfly	T.Viju, Paramankarai, Irenipuram(p.o).	2/9/2008	* Low Cost. * Long Life. * Smooth Speed Control.	* Low Quality. * Long time to heat the box. * No steam Iron.
23.	Aristocrat	Ocarina	R.Shygin, Kaithakattuvilai, Irenipuram(p.o).	3/9/2008	* Over Heating of Regulator. * Low Cost. * Maintainance Required.	* Smooth heat control. * High Cost. * Low Maintainance.
24.	Orient	Bajaj	T.Murugan, Kaithakattuvilai, Irenipuram(p.o).	3/9/2008	* Good looking. * Low Cost. * High quality.	* Less Weight. * Long Life. * High Quality.
25.	Polar	Alfa	A.David Raj, Kaithakattuvilai, Irenipuram(p.o).	3/9/2008	* Speed control is limited. * Less power. * Low cost.	* Less Weight. * Smooth Iron. * High Quality.
26.	Rallifan	National	S.Lawrence, Kaithakattuvilai, Irenipuram(p.o).	3/9/2008	* Humming Sound is heard. * Risk of Shock. * Low Cost.	* Smooth Heat Control. * Long Life. * Good Quality.
27.	Orient	National	A.Mohan, Kaithakattuvilai, Irenipuram(p.o).	3/9/2008	* Low Cost. * Long Life. * Smooth Speed Control.	* High Weight. * Smooth heat control. * No Maintainance.
28.	Polar	Anchor	D.Selva Raj, Kaithakattuvilai, Irenipuram(p.o).	3/9/2008	* Good mechanical strength. * Long life. * Low cost.	* Smooth Iron. * Less Weight. * High Quality.
29.	Crompton Greaves	Toshiba	A.Bright, Kaithakattuvilai, Irenipuram(p.o).	3/9/2008	* Low Cost * High Quality. * Good mechanical strength.	* Long Life. * Tough Heat Control. * Frequent Maintainance Required.
30.	Crompton Greaves	Alfa	P.Ghanaraj, Kaithakattuvilai, Irenipuram(p.o).	4/9/2008	* Low power consuming. * High quality. * Less sound is produced.	* Smooth Heat Control. * Long Life. * Good Quality.
31.	Crompton Greaves	Bajaj	S.Mani, Kaithakattuvilai, Irenipuram(p.o).	4/9/2008	* Smooth speed control. * Cool breeze. * Low cost.	* Low Cost. * No Maintainance. * Steam Iron.
32.	Breeze Cool	Elba	L.Vincent, Kaithakattuvilai, Irenipuram(p.o).	4/9/2008	* Low Quality. * Humming sound is heard. * Consume Large Power.	* Low Cost. * Long Life. * Good Quality.
33.	Usha	Pilot	P.Raesil Raj, Kaithakattuvilai, Irenipuram(p.o).	4/9/2008	* Low Cost. * Long Life. * Smooth Speed Control.	* Less Weight. * Long Life. * High Quality.

34.	Toshiba	Butterfly	A.P.Wilson, Kaithakattuvilai, Irenipuram(p.o).	4/9/2008	* Speed control is limited. * Less power. * Low cost.	* Smooth Iron. * Less Weight. * High Quality.
35.	Usha	National	R.Naveen, Indivaram, Painkulam(p.o).	4/9/2008	* Low Cost. * Long Life. * Smooth Speed Control.	* Warm Iron. * High Weight. * High Quality.
36.	Orient	Bajaj	A.Devaraj, Vadakanvilai, Puthukadai(p.o).	4/9/2008	* Low Cost. * No Sound. * Smooth Speed Control.	* High Weight. * Long Life. * High Quality.
37.	Orient	Philips	D.Selvaraj, Chattumukku, Painkulam(p.o).	4/9/2008	* Low mechanical strength. * High speed. * Good looking.	* High Cost. * Long Life. * Good Quality.
38.	Rallifan	National	F.Dharmalingam, Orikumpi vilai, Painkulam(p.o).	4/9/2008	* Consume less power. * Low cost. * Maintainance Required.	* Smooth Iron. * High Weight. * High Quality.
39.	Rallifan	Bajaj	W.Sunmugam, Aavaruvilai, Puthukadai(p.o).	4/9/2008	* Humming Sound is heard. * Risk of Shock. * Low Cost.	* Low Cost. * No Maintainance. * Steam Iron.
40.	Crompton Greaves	Toshiba	T.Raja Ram, Mundavilai, Kappukadu(p.o).	4/9/2008	* Smooth speed control. * Cool breeze. * Low cost.	* High Weight. * Less Stable. * No Maintainance.
41.	Orient	Philips	P.Santhosh, Kammakudi, Painkulam(p.o).	4/9/2008	* Good looking. * Low Cost. * High quality.	* Automatic Heat sensing. * Steam Iron. * High Quality.
42.	Usha	Toshiba	D.Thangamani, Manampalli, Painkulam(p.o).	5/9/2008	* Good mechanical strength. * Long life. * Low cost.	* Long Life. * Tough Heat Control. * Frequent Maintainance Required.
43.	Crompton Greaves	Bajaj	S.Kesavan, Kapikattu vilai, Puthukadai(p.o).	5/9/2008	* Low Cost. * Long Life. * Smooth Speed Control.	* High Cost. * Long Life. * Good Quality.
44.	Crompton Greaves	Philips	G.Ponnaiyan, Variyan vilai, PuthuKadai(p.o).	5/9/2008	* Low power consuming. * High quality. * Less sound is produced.	* Steam Iron. * Low power consuming. * Less weight.
45.	Orient	Alfa	A.K.Arun, Vallivilai, Keezhkulam(p.o).	5/9/2008	* Low Cost. * No Sound. * Smooth Speed Control.	* Low Cost. * No Maintainance. * Steam Iron.
46.	Toshiba	National	V.Sharisyan, Kootalumoodu, Painkulam(p.o).	5/9/2008	* Low Quality. * Humming sound is heard. * Consume Large Power.	* Smooth Heat Control. * Long Life. * Good Quality.
47.	Usha	National	X.Gunaseelan, Kootalumoodu, Painkulam(p.o).	5/9/2008	* Low Cost * High Quality. * Good mechanical strength.	* High Weight. * Long Life. * Good Quality.
48.	Breeze cool	Bajaj	H.Mahalingam, Vadalikootam, Keezhkulam(p.o).	5/9/2008	* Low Quality. * Low Current Consuming. * Sound while Operating.	* Automatic Heat sensing. * Safe operation. * Low Quality.
49.	Orient	Philips	T.Paulraj, Kadukaivilai, Painkulam(p.o).	5/9/2008	* Good looking. * Low Cost. * High quality.	* High Cost. * Long Life. * Good Quality.
50.	Orient	Philips	W.Satheesh, Kadukaivilai, Painkulam(p.o).	5/9/2008	* Good quality. * No Sound. * Wall fan also available.	* Automatic Heat sensing. * Steam Iron. * High Quality.
51.	Crompton Greaves	Toshiba	H.Radha Krisnan, Chattumukuvilai, Painkulam(p.o).	5/9/2008	* Good Quality. * Low Cost. * Less Sound while operation.	* Less Weight. * Long Life. * High Quality.

52.	Orient	National	K.Thangasamy, Mulancherri, Mulamkuzhi(p.o).	5/9/2008	* Low Cost. * No Sound. * Smooth Speed Control.	* Automatic Heat sensing. * Safe operation. * High Quality.
53.	Orient	Bajaj	S.Sundar Raj, Kovilvilai, Painkulam(p.o).	6/9/2008	* Good quality. * No Sound. * Wall fan also available.	* Low Cost. * No Maintainance. * Steam Iron.
54.	Crompton Greaves	Toshiba	T.Ponniyan, Karukanvilai, Painkulam(p.o).	6/9/2008	* Good Quality. * Low Cost. * Less Sound while operation.	* High Weight. * Less Stable. * Long Life.
55.	Toshiba	Bajaj	D.Chellapan, Vadaku Street, Painkulam(p.o).	6/9/2008	* Good looking. * Low Cost. * High quality.	* Low Cost. * No Maintainance. * Smooth speed control.
56.	Usha	Philips	S.Sam Raj, Karumvilagam, Painkulam(p.o).	6/9/2008	* Long Life. * High mechanical strength. * Good quality.	* High Cost. * Long Life. * Good Quality.
57.	Usha	Toshiba	D.Pallayan, Karumvilagam, Painkulam(p.o).	6/9/2008	* Good mechanical strength. * Long life. * Low cost.	* Long Life. * High Weight. * Frequent Maintainance Required.
58.	Toshiba	National	Y.Ravi, Karumvilagam, Painkulam(p.o).	6/9/2008	* Low mechanical strength. * Humming sound is heard. * Over heating of regulator.	* Smooth Heat Control. * Long Life. * Good Quality.
59.	Toshiba	Philips	N.Genil Elgio, Kovilvilai, Mulagumodu(p.o)	6/9/2008	* Low Cost. * Long Life. * Smooth Speed Control.	* Steam Iron. * Japan Technology. * Good Quality.
60.	Usha	National	R.Renjith, Kovilvilai, Mulagumodu(p.o)	6/9/2008	* High mechanical Strength. * Low Speed. * High Torque.	* Automatic Heat sensing. * Safe operation. * High Quality.
61.	Crompton Greaves	Bajaj	S.Sebastin, Kovilvilai, Mulagumodu(p.o)	6/9/2008	* Low power consuming. * High quality. * Less sound is produced.	* Low Cost. * No Maintainance. * Steam Iron.
62.	Toshiba	Anchor	S.Muthu, Kovilvilai, Mulagumodu(p.o)	6/9/2008	* Speed control is limited. * Less power. * Low cost.	* Automatic Heat sensing. * Risk of Electric Shock.. * Low Quality.
63.	Usha	Philips	R.Benjamin, Chandra Bhavan, Mulagumodu(p.o)	7/9/2008	* Low Cost * High Quality. * Good mechanical strength.	* Automatic Heat sensing. * Steam Iron. * High Quality.
64.	Crompton Greaves	Butterfly	S.Ramachandran, Pallivilai, Mulagumodu(p.o)	7/9/2008	* Good Quality. * Low Cost. * Less Sound while operation.	* Low Cost. * No Maintainance. * Steam Iron.
65.	Crompton Greaves	National	R.Mugesh, Pallivilai, Mulagumodu(p.o)	7/9/2008	* Good Quality. * High Cost. * Long life.	* Smooth Heat Control. * Long Life. * Good Quality.
66.	Rallifan	Toshiba	R.Jesus Romel, Pallivilai, Mulagumodu(p.o)	7/9/2008	* Humming Sound is heard. * Risk of Shock. * Low Cost.	* High Weight. * Less Stable. * Long Life.
67.	Polar	National	S.Selgin, Pallivilai, Mulagumodu(p.o)	7/9/2008	* Low Quality. * Humming sound is heard. * Consume Large Power.	* High Cost. * Long Life. * Good Quality.
68.	Usha	Bajaj	I.Ashok, Pallivilai, Mulagumodu(p.o)	7/9/2008	* Low Cost. * Good Quality. * Less Sound is Heard.	* Low Cost. * Smooth Heat Control. * Good Quality.
69.	Usha	Philips	S.Shamin Paul, Pallivilai, Mulagumodu(p.o)	7/9/2008	* High Quality. * Low cost . * Long life.	* Steam Iron. * Long Life. * Good Quality.

70.	Orient	Philips	R.Allwin, Pallivilai, Mulagumodu(p.o)	7/9/2008	* Low Cost. * No Sound. * Smooth Speed Control.	* Automatic Heat sensing. * Steam Iron. * High Quality.
71.	Crompton Greaves	Bajaj	A.Ebin, Koovaravilai, Mulagumodu(p.o)	7/9/2008	* Good Quality. * Low Cost. * Less Sound while operation.	* Low Cost. * No Maintainance. * Steam Iron.
72.	Usha	Toshiba	C.Anto, Koovaravilai, Mulagumodu(p.o)	7/9/2008	* Low Cost * High Quality. * Good mechanical strength.	* Less Weight. * No Maintainance Required. * High Quality.
73.	Usha	Elba	D.Biju, Koovaravilai, Mulagumodu(p.o)	7/9/2008	* Low Cost. * Good Quality. * Less Sound is Heard.	* Automatic Heat sensing. * Risk of Electric Shock.. * Low Quality.
74.	Crompton Greaves	Bajaj	R.Roy Mon, Koovaravilai, Mulagumodu(p.o)	7/9/2008	* Low power consuming. * High quality. * Less sound is produced.	* Smooth Heat Control. * Long Life. * Good Quality.
75.	Orient	National	V.Tiju Mon, Koovaravilai, Mulagumodu(p.o)	7/9/2008	* Good looking. * Wall fan also available. * Smooth Speed Control.	* High Cost. * Long Life. * Good Quality.
76.	Usha	Toshiba	P.Praveen, Koovaravilai, Mulagumodu(p.o)	7/9/2008	* High Quality. * Low cost . * Long life.	* Automatic Heat sensing. * Risk of Electric Shock.. * Low Quality.
77.	Orient	Philips	N.Jasreen, Koovaravilai, Mulagumodu(p.o)	7/9/2008	* Good quality. * No Sound. * Wall fan also available.	* Steam Iron. * Long Life. * Good Quality
78.	Usha	Anchor	T.Raj, Koovaravilai, Mulagumodu(p.o)	7/9/2008	* High mechanical Strength. * Low Speed. * High Torque.	* Low Cost. * No Maintainance. * Steam Iron.
79.	Crompton Greaves	Alfa	N.L.Ashok, Koovaravilai, Mulagumodu(p.o)	7/9/2008	* Less maintainance. * High Quality. * Smooth speed control.	* Frequent maintainance. * Risk of Electric Shock.. * Low Quality.
80.	Crompton Greaves	Toshiba	D.Nishanth, Koovaravilai, Mulagumodu(p.o)	8/9/2008	* Good Quality. * High Cost. * Long life.	* High Weight. * Heat Control is Complicated. * Good Quality
81.	Aristocrat	National	S.Sijil, Koovaravilai, Mulagumodu(p.o)	8/9/2008	* Low Quality. * Humming sound is heard. * Consume Large Power.	* Smooth Heat Control. * Long Life. * Good Quality.
82.	Crompton Greaves	Pilot	D.Mahesh, Koovaravilai, Mulagumodu(p.o)	8/9/2008	* Low Quality. * Low Current Consuming. * Sound while Operating.	* Automatic Heat sensing. * No Risk of Electric Shock.. * High Quality.
83.	Standard	Toshiba	R.Reegan, Koovaravilai, Mulagumodu(p.o)	8/9/2008	* Speed control is limited. * Less power. * Low cost.	* High Weight. * Less Stable. * No Maintainance.
84.	Orient	Philips	M.Ajin, Koovaravilai, Mulagumodu(p.o)	8/9/2008	* Dhoni is in ad for it. * Sound Less. * Cool Breeze.	* Steam Iron. * Long Life. * Less Weight
85.	Orient	Philips	R.Bright, Koovaravilai, Mulagumodu(p.o)	8/9/2008	* Low Cost. * Long Life. * Smooth Speed Control.	* Automatic Heat sensing. * Steam Iron. * High Quality.
86.	Polar	Toshiba	V.Kingsley, Koovaravilai, Mulagumodu(p.o)	9/9/2008	* Low mechanical strength. * Humming sound is heard. * Over heating of regulator.	* Low Quality. * Always having power problem. * Over heating.
87.	Usha	Bajaj	T.Satheesh, Manali, Thuckalay(p.o).	9/9/2008	* Low Cost * High Quality. * Good mechanical strength.	* Low Cost. * No Maintainance. * Steam Iron.

88.	Usha	Bajaj	T.Naveen Dinesh, Manali, Thuckalay(p.o).	9/9/2008	* High Quality. * Low cost . * Long life.	* Automatic Heat sensing. * No Risk of Electric Shock.. * High Quality.
89.	Polar	Toshiba	Shine.D.L.Singh, Manali, Thuckalay(p.o).	9/9/2008	* Humming sound is heard. * Over heating of regulator. * Low power is required.	* High weight. * Less Safe. * Risk of Fire.
90.	Rallifan	Philips	C.Dijo Benin, Manali, Thuckalay(p.o).	9/9/2008	* Consume less power. * Low cost. * Maintainance Required.	* Automatic Heat sensing. * Steam Iron. * High Quality.
91.	Rallifan	Philips	J.Suno Jaison, Eden Garden, Mulagumodu(p.o)	9/9/2008	* Speed control is limited. * Less power. * Low cost.	* Less Weight. * No Maintainance Required. * High Quality.
92.	Crompton Greaves	Toshiba	C.Cristo Nejatlin, Eden Garden, Mulagumodu(p.o)	10/9/2008	* Good Quality. * Low Cost. * Less Sound while operation.	* Less Weight. * Long Life. * High Quality.
93.	Toshiba	National	J.John Sujin, Eden Garden, Mulagumodu(p.o)	10/9/2008	* Low mechanical strength. * Humming sound is heard. * Over heating of regulator.	* Smooth Heat Control. * Long Life. * Good Quality.
94.	Toshiba	Butterfly	D.Anishmon, Eden Garden, Mulagumodu(p.o)	10/9/2008	* High mechanical Strength. * Low Speed. * High Torque.	* Low Cost. * No Maintainance. * Steam Iron.
95.	Rallifan	Bajaj	G.Shine, Eden Garden, Mulagumodu(p.o)	10/9/2008	* Humming Sound is heard. * Risk of Shock. * Low Cost.	* Low Cost. * Low power Consuming. * Less Weight.
96.	Crompton Greaves	Philips	D.Sunil, Eden Garden, Mulagumodu(p.o)	10/9/2008	* Low power consuming. * High quality. * Less sound is produced.	* Steam iron. * Less Weight. * Safe use.
97.	Toshiba	National	S.Dale Steyn, Eden Garden, Mulagumodu(p.o)	10/9/2008	* With in few years fault occurs * Problem with Regulator. * Over heating of regulator.	* High Cost. * Long Life. * High weight.
98.	Crompton Greaves	Philips	G.Smith, Eden Garden, Mulagumodu(p.o)	11/9/2008	* High Quality. * Low cost. * Low power consuming.	* Less Weight. * Long Life. * High Quality.
99.	Aristocrat	Butterfly	R.S.Shajimon, Kandankonam, Neyoor(p.o).	11/9/2008	* Low Quality. * Low Current Consuming. * Sound while Operating.	* Low Cost. * Frequent Maintainance Required. * High Speed.
100.	Crompton Greaves	Bajaj	D.Sajin Raj, Kandankonam, Neyoor(p.o).	11/9/2008	* Good Quality. * High Cost. * Long life.	* Low Cost. * No Maintainance. * Steam Iron.
101.	Honda	National	Y.Ajeesh, Kandankonam, Neyoor(p.o).	11/9/2008	* Speed control is Tough. * Fault in Regulator. * Capacitor problem occur.	* High Cost. * Long Life. * Good Quality.
102.	Mitasa	Toshiba	D.Shaji Kumar, Kandankonam, Neyoor(p.o).	11/9/2008	* Low Quality. * Humming sound is heard. * Consume Large Power.	* High Weight. * Less Stable. * Long Life.
103.	Rallifan	Toshiba	W.Felix, Kandankonam, Neyoor(p.o).	11/9/2008	* Good Quality. * Low Cost. * Long life.	* Long Life. * High Weight. * Frequent Maintainance Required.
104.	Aristocrat	Bajaj	R.Risser Roman, Kandankonam, Neyoor(p.o).	11/9/2008	* Low Quality. * Humming sound is heard. * Consume Large Power.	* Low Cost. * Low power Consuming. * Less Weight.
105.	Crompton Greaves	National	D.Subin, Kandankonam, Neyoor(p.o).	11/9/2008	* Low Cost. * Long Life. * Smooth Speed Control.	* Smooth Heat Control. * Long Life. * Good Quality.

106.	Crompton Greaves	Toshiba	J.Noble, Kandankonam, Neyoor(p.o).	11/9/2008	* Good Quality. * High Cost. * Long life.	* Heat Control is Complicated. * Over Heating. * Short life
107.	Breeze cool	National	J.Anderson Dev, Kandankonam, Neyoor(p.o).	11/9/2008	* Low Quality. * Low Current Consuming. * Sound while Operating.	* High Cost. * Long Life. * Good Quality.

Comparative Report:

- According to Our Report the Fan like most by the Consumers are Crompton Greaves and Usha. Comparing these two, most number of consumers like Crompton Greaves Fan because of Quality. But the Fan with less cost is Usha. The Fan which is less used by the consumers are Honda, Mitaso, Aristocrat, Breezecool and Standard because of quality.
- According to our Report on Ironbox Consumers like most the Philips, Bajaj, National Ironbox. Most number of consumers like Philips Ironbox because of quality but it high cost. Many consumers like Bajaj Ironbox because of less cost. Many consumers like National Ironbox because of long life. The Ironbox which are less used by the consumers are Elba, Occarina, Anchor, Vijay, Butterfly because of less quality.

Conclusion:

Thus according to our Report on Home Appliances such as Fan and Ironbox consumers like most the Philips Ironbox and Crompton Greaves Fan.

Submitted By,

**A.Sujin Jeya Kumar (90966697),
K.P.Reghu(90958064),**

St.Xaviers Catholic College of Engineering.